



Volunteer Patrol Vehicle Incident Investigation Summary

Case Number: C001
Date Assigned: 06/22/2026
Date Completed: 06/22/2026
Supervisor: Wong Heiman

I. INCIDENT INFORMATION

Incident Date: 06/19/2026
Incident Time: 21:20
Location: Flushing, Main St
Patrol Member(s): Hu, X
Vehicle Involved: Maserati
Patrol Assignment: Vehicle Patrol

II. NOTIFICATION

Supervisor Notified:
☒ Immediately ☐ Within 1 Hour ☐ Delayed
Time Notified: 21:30
Reported By: Hu, X

III. FACTUAL FINDINGS

Describe the facts gathered during the investigation:

Based on the NYPD accident report and scene photographs, the NYFA Volunteer Patrol Vehicle was traveling northbound on Main Street. The other vehicle, traveling ahead in the same direction, made a U-turn after the light turned green and collided with the NYFA patrol vehicle. After the accident, the other vehicle left the scene without stopping or exchanging information.

IV. STATEMENTS

Driver Statement Reviewed: ☒ Yes ☐ No
Witness Statements Reviewed: ☐ Yes ☒ No
Police Report Available: ☒ Yes ☐ No
Other Evidence: ☒ Photos ☐ Video ☐ Documents ☐ Other

V. CAUSE ANALYSIS

Primary Cause:
☐ Driver Error
☐ Traffic Conditions
☐ Weather
☐ Mechanical Problem
☒ Third Party Actions
☐ Unknown

VI. POLICY COMPLIANCE

Was NYFA policy followed?

☒ Yes ☐ No

Explanation:

After investigation, the NYFA Volunteer Patrol Vehicle was operating normally and in accordance with patrol mission requirements at the time of the incident. No violations of NYFA vehicle use policies, safety operation requirements, or patrol management procedures were identified. Following the incident, the involved personnel followed required procedures, including reporting the accident, preserving scene documentation, and cooperating with the follow-up investigation.

VII. INJURIES / DAMAGE

Injuries: ☒ None ☐ Minor ☐ Serious

Property Damage:

Front left wheel damaged; vehicle unable to turn left normally. Front end damage and heavy scratches observed.

Estimated Damage: \$ Unknown

VIII. SUPERVISOR FINDINGS

Based on the NYPD accident report, scene photographs, and vehicle damage assessment, the NYFA Volunteer Patrol Vehicle was traveling normally at the time of the incident. The other involved vehicle collided with the NYFA patrol vehicle while making a U-turn. After investigation, no violations of NYFA safety policies or improper operation by the NYFA driver were identified. The accident caused damage to the front and front left side of the NYFA patrol vehicle, and repair costs will be submitted to the responsible party's insurance company for a claim.

IX. RECOMMENDATIONS

- ☐ Additional Training
- ☐ Safety Counseling
- ☐ Policy Review
- ☒ No Further Action
- ☐ Administrative Review
- ☐ Other: _____

Supervisor Signature: _____

Date: 06/22/2026

Patrol Director Approval: _____

Date: 06/22/2026

